


Bench mark (X)-spike in birch tree at public access on east side of boat landing.
Assume elevation 100.0'
Water elevation 92.1'



EQUIPMENT	RECORDING SONAR	MAPPED	JUNE	1974
TOPOGRAPHIC SYMBOLS		LAKE BOTTOM SYMBOLS		
(B) Brush	Steep slope	P. Peat	B. Boulders	Stumps & Snags
(PW) Partially wooded	--- Indefinite shoreline	Mk. Muck	Rock danger to navigation	
(W) Wooded	Marsh	C. Clay	T. Submergent vegetation	
(C) Cleared	Spring	M. Marl	Emergent vegetation	
(P) Pastured	Intermittent stream	Sd. Sand	Floating vegetation	
(A) Agricultural	Permanent inlet	St. Silt	Brush shelters	
B.M. Bench Mark	Permanent outlet	Gr. Gravel		
• Dwelling	Dam	R. Rubble		
◻ Resort	D.N.R. State owned land	Br. Bedrock		

SPECIES OF FISH	Abundance		
	Abundant	Common	Present
Muskie			
N. Pike		X	
Walleye		X	
L. M. Bass	X		
S. M. Bass			
Panfish	X		

WATER AREA	516.5	ACRES
UNDER 2 FT.	65	%
OVER 20 FT.		%
MAX. DEPTH	10	FEET.
TOTAL ALK.	69	P.P.M.
VOLUME	1147.66	ACRE FT.
MAIN SHORELINE	409	



Access Access with Parking Boat Livery
Drawn by: W. Berwig